

**Photographs taken by V Carty on 23/07/15
at the Red Lion 261, Chatsworth Road**

Areas of damaged flooring in public areas of the bars;



Damaged flooring in public areas of the bars – continued;



Damaged flooring behind bar;



Hole in wall of ladies toilets;



Dirty sink and areas behind bar dirty;



Mouldy sliced lemons with flies and mouldy lemons in chiller;



Animal faeces in beer garden/smoking shelter;

