


GAS SAFETY RECORD SHEET

Chesterfield Borough Council Building Services



This inspection is for gas safety purposes only in accordance with Gas Safety (Installation and Use) Regulations. Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has not been carried out.

Safety checked by: **Chesterfield Borough Council**
 Building Services
 Stonegravels Lane
 Chesterfield
 S41 7LF Tel: (01246) 345048

Gas Safe Reg. No. **1 3 7 9 8**

I certify that I carried out inspections on the listed appliances on: **12/11/18**
 Signed: **[Signature]** (Date of inspection)

TENANTS
 Name: **[Redacted]**
 Address: **[Redacted]**

Chesterfield unknown

LANDLORD (OR WHERE APPROPRIATE THEIR AGENT)
 Chesterfield Borough Council
 Town Hall
 Rose Hill
 Chesterfield S40 1LP
 Tel: (01246) 345408

104656

APPLIANCES

Number	LOCATION	TYPE	MAKE	MODEL	FLUE TYPE FF, BF, CF	Operating Pressure or Heat input BTU/Hr	Safety Device Correct Operation Yes/No	Ventilation Satisfactory Yes/No	Visual Condition of Flue Pass/Fail	FLUE PERFORMANCE CHECK		Termination Satisfactory Yes/No	Appliance Safe to Use Yes/No	Inspected Yes/No
										Flue Flow Test Pass/Fail	Spillage Test Pass/Fail			
1	Kitchen	Combi	Worthington	281	CF	19	Y	Y	Pass	N/A	N/A	Y	Y	Y
2	Kitchen	cooker	Newworld	Newhome	(NO)	Visible								
3														

DETAILS OF ANY FAULTS

REMEDIAL ACTION TAKEN

Warning Notice Issued YES/NO

Earth bonding YES NO
 Meter markings YES NO
 Gas pipe sleeved YES NO
 Gas pipe sealed YES NO
 Let By Test ECV YES NO

Gas installation: tightness test **PASS** **FAIL** Meter Standing Pressure **25** m/bar Meter Working Pressure **20** m/bar

This Safety record is issued by Signed: **[Redacted]** Print name: **[Redacted]** Date: **12/11/18**
 Received on behalf of the Landlord Signed: **[Redacted]** Tenant/Agent/Landlord

Key White Copy - Landlord, Pink Copy - Installer, Yellow Copy - Tenant

Vessel Check **Y** **N/A** bar

Boiler Installation Date	2005-2015
Radiator Condition	B

CO ₂ High	9.6	CO ₂ Low	9	Ratio	0.0006	O ₂ /Flue Integrity	20.9 %
----------------------	------------	---------------------	----------	-------	---------------	--------------------------------	---------------

Number of Appliances Tested **01**